

Dependent Resurvey of the E. Bdy., T. 45 N., R. 36 E.

Chains

T46N R37E

S31

S 1 | S 6

R36E R37E

T45N

CC

1956

From this corner, the standard township corner of T. 46 N., Rs. 36 and 37 E., which is monumented with an iron post, 2½ ins. diam., set, mkd. and witnessed as previously described, bears N. 89° 38' W., 3.38 chs. dist.

Land, hilly; broken with ledges.
Soil, rocky loam.
Timber, none; undergrowth, sagebrush.

Dependent Resurvey of the E. Bdy., T. 45 N., R. 37 E.

Reestablishment of the survey executed by O. A. Palmer in 1868.

From the cor. of Ts. 44 and 45 N., Rs. 37 and 38 E., which is monumented with an iron post, 3 ins. diam., previously described.

N. 1° 56' W., bet. secs. 31 and 36.

Along gentle rolling W. slope, through heavy undergrowth; desc. 10 ft.

40.05 Point for the ¼ sec. cor. of secs. 31 and 36, at proportionate dist.; there is no remaining evidence of the original corner.

Set an iron post, 30 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.

T45N

R37E R38E

¼

S36 | S31

1956

Deposit broken glass at base of post.

Desc. 10 ft.

80.11 Point for the cor. of secs. 25, 30, 31 and 36, at proportionate dist.; there is no remaining evidence of the original corner.

Set an iron post, 30 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.

T45N

R37E R38E

S25 | S30

S36 | S31

1956

Deposit broken glass at base of post.

Land, gentle rolling.
Soil, sandy.
Timber, none; undergrowth, sagebrush.