

Independent Resurvey of the E. Bdy., T. 45 N., R. 37 E.

Chains

Land, level.
Soil, sandy.
Timber, none; undergrowth, sagebrush, crested wheat grass.

N. 1° 56' W., bet. secs. 7 and 12.

Across level land, through heavy undergrowth.

6.26 Wash, 15 lks. wide, 1½ ft. deep, drains W.

40.05 Point for the ¼ sec. cor. of secs. 7 and 12, at proportionate dist.; there is no remaining evidence of the original corner.

Set an iron post, 30 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.

T45N
R37E R38E

¼
S 12 | S 7
1956

Deposit broken glass at base of post.

78.43 Wash, 10 lks. wide, 1 ft. deep, drains W.

80.11 Point for the cor. of secs. 1, 6, 7 and 12, at proportionate dist.; there is no remaining evidence of the original corner.

Set an iron post, 30 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.

T45N
R37E R38E

S 1 | S 6
S 12 | S 7
1956

Deposit broken glass at base of post.

Land, level.
Soil, sandy.
Timber, none, undergrowth, sagebrush.

N. 1° 56' W., bet. secs. 1 and 6.

Over level land, through heavy undergrowth.

40.05 Point for the ¼ sec. cor. of secs. 1 and 6, at proportionate dist.; there is no remaining evidence of the original corner.

Set an iron post, 30 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.

T45N
R37E R38E

¼
S 1 | S 6
1956

Deposit broken glass at base of post.

Desc. 10 ft.