

Dependent Resurvey of a Portion of the Subdivision, T. 45 N., R. 37 E.

Chains

Land, nearly level.
Soil, sandy.
Timber, none; undergrowth, sagebrush.

N. 2° 06' W., bet. secs. 1 and 2.

Across nearly level land, through heavy undergrowth.

2.19 Wash, 4 lks. wide, 1½ ft. deep, drains W.

40.06 Point for the ¼ sec. cor. of secs. 1 and 2, at proportionate dist.; there is no remaining evidence of the original corner.

Set an iron post, 30 ins. long, 2½ ins. diam., 20 ins. in the ground, with brass cap mkd.

T45N R37E

¼
S 2 | S 1
1956

Deposit broken glass at base of post.

81.98 Intersect the Ninth Standard Parallel North.

Point for the closing cor. of secs. 1 and 2.

Set an iron post, 30 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.

T46N R37E

S35
S 2 | S 1
T45N R37E
C C
1956

Deposit broken glass at base of post.

From this cor., the standard corner of secs. 35 and 36, T. 46 N., R. 37 E., which is monumented with an iron post, 2½ ins. diam., set, mkd. and witnessed as previously described, bears S. 89° 38' E., 4.51 chs. dist.

Land, level.
Soil, sandy.
Timber, none; undergrowth, sagebrush.

At the point for the N. ¼ sec. cor. of sec. 1, on the N. bdy. of the township, at proportionate dist., at 40.11 chs. easting from the closing cor. of secs. 1 and 2.

Set an iron post, 30 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.

T46N R37E

¼ S 1
T45N R37E
1956

Deposit broken glass at base of post.

From this cor., the standard ¼ sec. cor. of sec. 36, which is monumented with an iron post, 2½ ins. diam., set, mkd. and witnessed as previously described, bears S. 89° 38' E., 4.54 chs. dist.