

## Dependent Resurvey of a Portion of the Subdivision, T. 45 N., R. 37 E.

Chains

Over river bottom land, through heavy undergrowth of rye grass, scattered sage and rabbit brush, greasewood.

13.63 Quinn River, dry, 40 lks. wide, banks 6 ft. high, course S. 30° W.; asc. 10 ft.

39.88 True point for the  $\frac{1}{4}$  sec. cor. of secs. 2 and 3, at proportionate dist.; there is no remaining evidence of the original corner; true point falls in a dry slough, 25 lks. wide, 3 ft. deep.

40.88 Point for the witness  $\frac{1}{4}$  sec. cor. of secs. 2 and 3.

Set an iron post, 30 ins. long, 2 $\frac{1}{2}$  ins. diam., 22 ins. in the ground, with brass cap mkd.

T45N R37E.

$\frac{1}{4}$   
S 3 | S 2  
W C  
1956

Deposit broken glass at base of post.

47.80 Wire fence, bears E. and W.

47.90 Ungraded road, bears E. and W.; asc. 20 ft.

52.09 River bottom line, bears E. and W.; leave grass, greasewood; desc. 10 ft.

81.56 Intersect the Ninth Standard Parallel North.

Point for the closing cor. of secs. 2 and 3.

Set an iron post, 30 ins. long, 2 $\frac{1}{2}$  ins. diam., 20 ins. in the ground, with brass cap mkd.

T46N R37E

S34  
S 3 | S 2  
T45N R37E  
C C  
1956

Deposit broken glass at base of post.

From this corner, the standard corner of secs. 34 and 35, T. 46 N., R. 37 E., which is monumented with an iron post, 2 $\frac{1}{2}$  ins. diam., set, mkd. and witnessed as previously described, bears S. 89° 38' E., 4.62 chs. dist.

Land, nearly level.

Soil, sandy.

Timber, none; undergrowth, sagebrush, rye grass, scattered rabbit brush and greasewood.

At the point for the N.  $\frac{1}{4}$  sec. cor. of sec. 2, on the N. bdy. of the township, at proportionate dist., at 40.19 chs. easting from the closing cor. of secs. 2 and 3.

Set an iron post, 30 ins. long, 2 $\frac{1}{2}$  ins. diam., 24 ins. in the ground, with brass cap mkd.

T46N R37E

$\frac{1}{4}$  S 2  
T45N R37E

1956