

Survey of a Portion of the Subdivision, T. 45 N., R. 37 E.

Chains

T45N R37E

 $\frac{1}{4}$
 S 5 | S 4
 1956

Deposit broken glass at base of post.

Continue to desc. NW. slope; desc. 40 ft.

46.40 Base of slope; asc. 190 ft. up SW. slope.

62.50 Top of slope; desc. 40 ft. along NW. slope.

77.92 Wash, 10 lks. wide, 3 ft. deep, drains W.

79.03 Intersect the Ninth Standard Parallel North.

Point for the closing cor. of secs. 4 and 5.

Set an iron post, 30 ins. long, 2½ ins. diam., 6 ins. in the ground to bedrock, and in a mound of stone, 3½ ft. base to top, with brass cap mkd.

T46N R37E

 $\frac{1}{4}$
 S 5 | S 4
 T45N R37E
 C C
 1956

From this cor., the standard cor. of secs. 32 and 33, T. 46 N., R. 37 E., which is monumented with an iron post, 2½ ins. diam., set, mkd. and witnessed as previously described, bears N. 89° 38' W., 1.19 chs. dist.

Land, hilly.

Soil, sandy loam.

Timber, none; undergrowth, sagebrush.

At the point for the N. ¼ sec. cor. of sec. 4, on the N. bdy. of the township, at 40.00 chs. easting from the closing cor. of secs. 4 and 5.

Set an iron post, 30 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.

 $\frac{1}{4}$ S 4
 T45N R37E
 1956

Raise a mound of stone, 3 ft. base, 2½ ft. high, to S.

From this cor., the standard ¼ sec. cor. of sec. 33, T. 46 N., R. 37 E., which is monumented with an iron post, 2½ ins. diam., set, mkd. and witnessed as previously described, bears N. 89° 38' W., 1.19 chs. dist.

Dependent Resurvey of a Portion of the Subdivision, T. 45 N., R. 37 E.

From the cor. of secs. 5, 6, 31 and 32, on the S. bdy. of the township.

N. 0° 15' E., bet. secs. 31 and 32.