

Dependent Resurvey of the North Boundary, T. 46 N, R. 38 E.

Chains	
29.00	Quinn River, 1.20 chs. wide, 8 ft. deep, drains S. 30° W.
40.96	Point for $\frac{1}{4}$ sec. cor. of secs. 6 and 31, at proportionate dist.; there is no remaining evidence of the original cor. Set an iron post, 30 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd. T47N R38E $\frac{1}{4}$ $\frac{S31}{S6}$ T46N R38E 1957
81.52	The cor. of Ts. 46 and 47 N., Rs. 37 and 38 E. Land, flat. Soil, loam. Vegetation, meadow grass, sagebrush and bull berry bushes.

Dependent Resurvey of the Subdivisional Lines, T. 46 N, R. 38 E.

	Reestablishment of the survey executed by O. A. Palmer, Deputy Surveyor, in 1869. From the cor. of secs. 35 and 36, on the S. bdy. of the Tp. N. 0° 45' W., bet. secs. 35 and 36. Over gently rolling hills.
7.78	Dry wash, 10 lks. wide, 2 ft. deep, drains S. 80° W.
11.68	Creek, 1.00 ch. wide, 4 ft. deep, drains S. 60° W.
15.58	Dry wash, 20 lks. wide, 3 ft. deep, drains S. 70° W.
17.48	Unimproved road, bears S. 70° W. and N. 70° E.
24.98	Dry wash, 10 lks. wide, 2 ft. deep, drains W.
40.35	Point for $\frac{1}{4}$ sec. cor. of secs. 35 and 36, at proportionate dist.; there is no remaining evidence of the original cor. Set an iron post, 30 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd. T46N R38E $\frac{1}{4}$ $\frac{S35}{S36}$ 1957
43.63	Unimproved road, bears N. 15° E. and S. 15° W.
45.03	Dry wash, 8 lks. wide, 2 ft. deep, drains W.
56.33	Dry wash, 8 lks. wide, 1 ft. deep, drains W.
80.70	Point for the cor. of secs. 25, 26, 35 and 36, at proportionate dist.; there is no remaining evidence of the original cor. Set an iron post, 30 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd. T46N R38E $\frac{S26}{S35}$ $\frac{S25}{S36}$ 1957