

Dependent Resurvey,
S. Bdy., T. 19 S., R. 58 E.

Chains	
39.87	<p>The cor. of Ts. 19 and 20 S., Rs. 57 and 58 E., an iron post, 3 ins. diam., firmly set, mkd. and witnessed as described in the official record.</p> <p>Land, mountainous. Soil, rocky clay. Timber, none; undergrowth, scattered juniper and pinon.</p>
	<p>General Description</p> <p>The south boundary of T. 19 S., R. 58 E., falls along the north side of La Madre Mountain, crossing numerous washes and spurs, but staying at a general elevation of about 5200 ft. above sea level.</p> <p>The soil is a rocky clay; the vegetation consists of buck brush, blackbrush, sparse grass and scattered pinon and juniper.</p> <p>There are three access roads crossing the boundary, one each on the south boundary of sections 31, 32 and 33.</p>