Dependent Resurvey, Subdivision, T. 19 S., R. 59 E.

AN N	
Chains	
76.10	Wash, 70 lks. wide, 4 ft. deep, drains N. 60° E.
80.78	Point for the cor. of secs. 25, 26, 35 and 36, at proportionate distance; there is no remaining evidence of the original cor.
	Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 14 ins. in the ground to bedrock, and in a mound of stone to top, with brass cap mkd.
	T19S R59E S26 S25 S35 S36 1956
	Land, nearly level. Soil, gravelly. Timber, none; undergrowth, creosote brush, yucca and cacti.
,	From the cor. of secs. 25, 30, 31 and 36, on the E. bdy. of the Tp., an iron post, $2\frac{1}{2}$ ins. diam., set, mkd. and witnessed as described in the field note record of the resurvey of the W. bdy. of T. 19 S., R. 60 E.
	S. 89° 26' W., bet. secs. 25 and 36.
	Asc. 97 ft. over gradual E. slope to 1 sec. cor.
40.86	Point for the 4 sec. cor. of secs. 25 and 36, at proportionate distance; there is no remaining evidence of the original cor.
	Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.
*	1 S25 S36 1956
	Raise a mound of stone, 3 ft. base, 2 ft. high, N. of cor.
	Asc. 124 ft. over gradual E. slope to sec. cor.
67.20	Wash, 20 lks. wide, 8 ft. deep, drains N. 40° E. approximately 4 chs. to another wash.
75.00	Wash, 60 lks. wide, 3 ft. deep, drains N. 35° E. approximately 8 chs. to other wash.
61.72	The cor. of secs. 25, 26, 35 and 36.
,	Land, nearly level. Soil, gravelly. Timber, none; undergrowth, creosote brush, cacti and yucca.
	N. 0° 26' W., bet. secs. 25 and 26.
at a	Over nearly level land; desc. 16 ft. to 1/2 sec. cor.
7.30	Wash, 50 lks. wide, 8 ft. deep, drains S. 70° E.; junction of 3 small washes from W.
14.30	W. slope of small limestone knoll.