

Dependent Resurvey,  
Subdivision, T. 19 S., R. 59 E.

Chains

T19S R59E  
S11|S12  
S14|S13  
1956

Land, nearly level.  
Soil, gravelly.  
Timber, none; undergrowth, creosote brush, cacti and yucca.

From the cor. of secs. 7, 12, 13 and 18, on the E. bdy. of the Tp., an iron post, 2½ ins. diam., set, mkd. and witnessed as described in the field note record of the resurvey of the W. bdy. of T. 19 S., R. 60 E.

S. 87° 59' W., bet. secs. 12 and 13.

Asc. 99 ft. over gradual E. slope to ¼ sec. cor.

41.66 Point for the ¼ sec. cor. of secs. 12 and 13, at proportionate distance; there is no remaining evidence of the original cor.

Set an iron post, 30 ins. long, 2½ ins. diam., 8 ins. in the ground to bedrock, and in a mound of stone to top, with brass cap mkd.

¼  $\frac{S12}{S13}$   
1956

62.49 Asc. 110 ft. over gradual E. slope to sec. cor.

83.32 Road, bladed, bears N. and S.

The cor. of secs. 11, 12, 13 and 14.

Land, nearly level.  
Soil, gravelly.  
Timber, none; undergrowth, creosote brush, cacti and yucca.

N. 1° 14' E., bet. secs. 11 and 12.

Over nearly level land.

7.00 Shallow wash, drains E.

15.00 Wash, 10 lks. wide, 1 ft. deep, drains E.

17.00 Wash, 10 lks. wide, 1 ft. deep, heads approximately 5 chs. W., drains S. 65° E., approximately 2 chs. to other wash.

22.20 Wash, 20 lks. wide, 5 ft. deep, drains N. 85° E.

23.30 Wash, 20 lks. wide, 3 ft. deep, drains E. approximately 2 chs. to other wash.

30.10 Wash, 40 lks. wide, 15 ft. deep, drains E.

38.10 Wash, 7 lks. wide, 2 ft. deep, drains E.

40.47 The ¼ sec. cor. of secs. 11 and 12, mkd. by the original stone, a limestone, 14 x 6 x 6 ins., mkd. ¼ on N. side and set in a mound of stone.

At the corner point