

336

Dependent Resurvey of the East Boundary, T. 22 S., R. 58 E.

Chains	
27.22	Right bank of deep wash, bears NNW. and SSE.
27.72	Main channel of wash, 30 lks. wide, 5 ft. deep, drains ESE.
29.00	Left bank of wash, bears NNW. and SSE.
37.00	Graded graveled road, bears NW. and SE., in bottom of wash, 30 lks. wide, 3 ft. deep, drains SSW.
40.55	The cor. of secs. 1, 6, 7 and 12, which is mkd. by a limestone, 24x12x10 ins., firmly set in the ground, near the right bank of a wash, mkd. and witnessed as defined in the 1881 survey record. At the cor. point Set an iron post, 30 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd. T22S R58E R59E S 1 S 6 S12 S 7 1956 Raise a mound of stone, 6 ft. base, 3 ft. high, W. of cor., and re-set original cornerstone alongside the iron post. Land, rolling mountainous. Soil, sandy and gravelly loam. Timber, none. Undergrowth, sagebrush, yucca and cactus.
<hr/>	
	N. 6° 47' W., bet. secs. 1 and 6.
	Over rolling mountainous land, through medium heavy undergrowth.
2.00	Wash, 30 lks. wide, 6 ft. deep, drains SSE.; asc. 72 ft. over S. slope.
24.02	Wash, 30 lks. wide, 5 ft. deep, drains SW. into main wash.
33.42	Graded road, bears NW. and SE.
42.00	Shoulder of spur, slopes W.
43.13	Point for the ¼ sec. cor. of secs. 1 and 6, at proportionate dist.; there is no remaining evidence of the original cor. Set an iron post, 30 ins. long, 2½ ins. diam., 18 ins. in the ground, to solid rock, and in a mound of stone to top, with brass cap mkd. ¼ S 1 S 6 1956
45.55	Wash, 2 chs. wide, 30 ft. deep, drains SSW.; asc. 144 ft. over S. slope.
46.82	Road, bears NE. and SSW.
50.05	Road, bears SW. and NE.
71.25	Same road, bears N. and S., on top of spur, slopes ESE.; desc. 17 ft. over N. slope.