

Dependent Resurvey of the East Boundary, T. 22 S., R. 58 E.

Chains	
78.00	Same road, bears NNW. and S.
79.00	Gulch, 50 lks. wide, drains SE.; asc. 38 ft. over SW. slope to cor.
86.26	The cor. of Ts. 21 and 22 S., Rs. 58 and 59 E., which is mkd. by a limestone, 24x14x10 ins., firmly set in a mound of stone, mkd. and witnessed as defined in the 1881 survey record.
	At the cor. point
	Set an iron post, 30 ins. long, 2½ ins. diam., 3 ins. in the ground, to solid rock, and in a mound of stone to top, with brass cap mkd.
	T21S R58E R59E <u>S36 S31</u> S1 S6 T22S 1956
	Reset the original cornerstone alongside the iron post.
	Land, rolling mountainous.
	Soil, sandy and gravelly loam.
	Timber, none.
	Undergrowth, cactus, yucca and sagebrush.

Dependent Resurvey of the South Boundary, T. 22 S., R. 58 E.

	Reestablishment of the survey executed by Brunt and Proctor, Deputy Surveyors, in 1881.
	From the cor. of Ts. 22 and 23 S., Rs. 58 and 59 E., hereinbefore described.
	S. 88° 46' W., bet. secs. 1 and 36.
	Over mountainous land, through medium heavy undergrowth; desc. 150 ft. over steep rocky W. slope.
6.30	Bottom of descent, bears NW. and SE.; begin ascent; asc. 200 ft. over E. slope.
12.00	Small spur, slopes SE.; cont. ascent.
15.00	Head of gully, drains SE.; cont. ascent; asc. 600 ft. over E. slope.
36.00	Top of spur, slopes SSW.; desc. over gradual W. slope to cor.
40.17	The ¼ sec. cor. of secs. 1 and 36, which is mkd. by a limestone, 18x12x8 ins., firmly set in a mound of stone, mkd. and witnessed as defined in the 1881 survey record.
	At the cor. point
	Set an iron post, 30 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.
	<u>S 39</u> S 1 1956
	Raise a mound of stone, 5 ft. base, 3 ft. high, N. of cor., and reset original cornerstone alongside the iron post.