

Dependent Resurvey of the North Boundary of T. 16 S., R. 49 E.

Chains	
27.70	Wash, 40 lks. wide, 3 ft. deep, drains SW.
39.97	<p>The original $\frac{1}{4}$ sec. cor. of secs. 6 and 31, which is mkd. by an iron post, 1 in. diam., 10 ins. above ground, firmly set, mkd. and witnessed as described in the 1921 survey record. This corner will now serve as the $\frac{1}{4}$ sec. cor. of sec. 6 only. I alter the markings on the brass cap to read</p> <p style="text-align: center;">T15S R49E $\frac{1}{4}$ S 6 T16S R49E 57 1921</p>
43.00	Wash, 20 lks. wide, 2 ft. deep, drains SW.
50.90	Wash, 6 lks. wide, 6 ins. deep, drains SW.
55.68	<p>Point for the $\frac{1}{4}$ sec. cor. of sec. 31, T. 15 S., R. 49 E.</p> <p>Set an iron post, 30 ins. long, 2$\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.</p> <p style="text-align: center;">T15S R49E $\frac{1}{4}$ S31 T16S R49E 1957</p> <p>Raise a mound of stone, 3 ft. base, 1$\frac{1}{2}$ ft. high, N. of cor.</p>
64.48	Wash, 20 lks. wide, 3 ft. deep, drains SSW.
79.96	<p>The cor. of Ts. 15 and 16 S., Rs. 48 and 49 E., which is mkd. by an iron post, 3 ins. diam., 10 ins. above ground, firmly set, mkd. and witnessed as described in the 1921 survey record.</p> <p>Land, nearly level. Soil, sandy and volcanic ash. Timber, none; undergrowth, creosote bush and sagebrush.</p>
Survey of the West Boundary of T. 15 S., R. 49 E.	
<p>From the cor. of Ts. 15 and 16 S., Rs. 48 and 49 E., which is mkd. by an iron post, 3 ins. diam., firmly set, hereinbefore described.</p> <p>North, on true line, bet. secs. 31 and 36.</p> <p>Over nearly level land, through heavy undergrowth.</p>	
18.50	Wash, 30 lks. wide, 2 ft. deep, drains SW.
38.70	Wash, 30 lks. wide, 3 ft. deep, drains SW.
40.00	Point for the $\frac{1}{4}$ sec. cor. of secs. 31 and 36.