

## Dependent Resurvey, E. Bdy., T. 45 N., R. 33 E.

Chains

Set an iron post 30 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.

T45N  
R33E R34E  
S 1 | S 6  
S 12 | S 7  
1958

Land, nearly level.  
Soil, sandy loam.  
Vegetation, thick sagebrush.

N. 0° 32' E., bet. secs. 1 and 6.

Over level land, through thick sagebrush.

- 40.37 Point for the ¼ sec. cor. of secs. 1 and 6, at proportionate dist.; there is no remaining evidence of the original cor.
- Set an iron post 30 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.

T45N  
R33E R34E  
¼  
S 1 | S 6  
1958

- 67.54 Unimproved road bears S. 45° E. and N. 45° W.

- 80.74 Intersect 9th Standard Parallel North at the closing cor. of secs. 1 and 6, T. 45 N., Rs. 33 and 34 E., mkd. by I. P. 3 ins. in diam., extending 4 ins. above ground, firmly set and mkd. as described in the official record of T. 46 N., R. 34 E.

From the point of intersection the standard ¼ sec. cor. of sec. 31, T. 46 N., R. 34 E., monumented with an iron post, 1 in. diam., as described in the official record, bears N. 89° 01' W., 3.96 chs.

From the same point, the standard cor. of T. 46 N., Rs. 33 and 34 E., bears N. 89° 01' W., 6.46 chs.

Land, level.  
Soil, sandy loam.  
Vegetation, thick sagebrush.

Dependent Resurvey of a Portion of the S. Bdy. of T. 46 N., R. 33 E.  
(9th Standard Parallel North)

Reestablishment of the survey executed by G. W. Garthside and C. L. Preble in 1874.

From the standard cor. of T. 46 N., Rs. 33 and 34 E.

N. 89° 10' W., along S. bdy. of sec. 36.

Over nearly level land.

- 19.82 Dry wash 10 lks. wide, 2 ft. deep, drains S.
- 20.31 Ditch 25 lks. wide, 3 ft. deep, drains S. 20° E.
- 34.01 Point for the ¼ sec. cor. of sec. 1, hereinafter described; thence N. 89° 10' W. along old net wire fence.