

363

Dependent Resurvey of the East Boundary of T. 25 S., R. 61 E.
(West Boundary of T. 25 S., R. 62 E.)

Chains

N. 1° 28' W., along the E. bdy. of sec. 1, T. 25 S.; R. 61 E. (W. bdy. sec. 6, T. 25 S., R. 62 E.)

Over rolling, broken, mountainous land, through scattered undergrowth.

Asc. 226 ft. over SE. slope.

14.63 Top of ascent, slopes E.; desc. 253 ft. over NE. slopes.

40.17 The original 1/4 sec. cor. of secs. 1 and 6, which is mkd. with a basalt stone, firmly set in a mound of stone, mkd. and witnessed as described in the official record. This cor. will now function for the 1/4 sec. cor. of sec. 1 only.

At the cor. point

Set an iron post, 30 ins. long, 2 1/2 ins. diam., 4 ins. in the ground to solid rock, in a mound of stone to top, with brass cap mkd.

T25S

R61E

S1 | R62E

1958

Reset the original cornerstone alongside the iron post.

N. 1° 49' E., beginning new measurement.

Cont. over broken, mountainous land; desc. 175 ft. over NE. slope.

12.20 Begin ascent; asc. 39 ft. over SE. slope.

33.97 Wash, 50 lks. wide, 10 ft. deep, drains SE.; asc. 130 ft. over SW. slope.

41.38 The original closing cor. of Tps. 25 S., Rs. 61 and 62 E., on the N. bdy. of the Tp., which is mkd. with a basalt stone firmly set in the ground and in a mound of stone, mkd. and witnessed as described in the official record.

At the cor. point

Set an iron post, 30 ins. long, 2 1/2 ins. diam., 4 ins. in the ground to solid rock, in a mound of stone to top, with brass cap mkd.

T24S

R61E

S36

S 1 | S 6

C C

R61E R62E

T25S

1958

From this cor. the standard cor. of Tps. 24 S., Rs. 61 and 62 E., which is mkd. with an iron post, 3 ins. diam., firmly set in the ground, mkd. and witnessed as described in the official record, bears S. 80° 33' E., 13.62 chs. dist.

Land, rolling and broken mountainous.

Soil, sandy and gravelly, stony.

Timber, none.

Undergrowth, cactus and creosote bush.