Survey of the East Boundary of T. 19 S., R. 65 E.

		Survey of the East Boundary of T. 19 S., R. 65 E.
	Chains	
		T19S
		R65E R66E
·		S1 S6
		S12 S7 1958
	1	
		Land, rolling
		Soil, shallow, gravelly
		Timber, none
	And 3 1 200 A	
-		North bet. secs. 1 and 6.
		Description of the state of the
		Desc. 80 ft. along E. slope.
	22.00	Bottom of desc.; asc. 30 ft. along E. slope.
	25.50	Low spur, slopes E. 3.00 chs.; desc. 40 ft. along NE. slope.
	40.00	Point for the 2 sec. cor. of secs. 1 and 6, falls in bottom of wash, draining E, where cor. cannot be perpetuated.
	40.60	Point selected for the witness 1/2 sec. cor. of secs. 1 and 6.
		Set an iron post 30 ins. long, $2\frac{1}{2}$ ins. diam. 15 ins. in the ground and in a collar of stone with brass cap marked
		T19S R65E R66E
		kosi kosi Ž
		S1 S6
		W C
		1958
		Cont. along E. slope; desc. 20 ft.
١.	63.10	Wash, 6 ft. deep, 40 lks. wide, drains E; cont. along E. slope over series of spurs and small washes; asc. 50 ft.
1.	76.10	Flat top spur, slopes NE; desc. 40 ft. along NW slope.
	80.00	Point for the Tp. cor. of Tps. 18 and 19 S., Rs. 65 and 66 E.
		Set an iron post 30 ins. long, $2\frac{1}{2}$ ins. diam. 6 ins. in the ground to bedrock and in a mound of stone, 4 ft. base to top of cap, with brass cap marked
		T18S
		R65E R66E
	· 3	<u>836 831 </u>
		S1 S6
		T19S 1958
		. 1930
		Land, rolling
	7	Soil, shallow, gravelly
		Timber, none
	- W 100 S	
		[2] [1] [2] [2] [2] [2] [2] [2] [2] [2] [2] [2