

Independent Resurvey of the Subdivision of T. 17 S., R. 63 E.

Chains

From this cor. the standard $\frac{1}{4}$ sec. cor. on the S. bdy. of sec. 34, T. 16 S., R. 63 E., bears W. 16.06 chs. dist., an iron post, 1 in. diam., set, mkd. and witnessed as described in the official record.

The $\frac{1}{4}$ sec. cor. on the N. bdy. of sec. 3, T. 18 S., R. 63 E., an iron post, set, mkd. and witnessed as described in the official record, was remarked in accordance with the special instructions.

T17S R63E

$\frac{1}{4}$ S34

S. 3

T18S R63E

1958

From the closing cor. of secs. 3 and 4, T. 18 S., R. 63 E., an iron post, 3 ins. diam., set, mkd. and witnessed as described in the official record. In accordance with the special instructions this cor. was remarked.

T17S R63E

S33 | S34

S4 | S3

T18S

1958

N. 0° 02' W., bet. secs. 33 and 34.

Over rolling desert land; asc. E. slope.

11.70 Wash, 3 ft. deep, 30 lks. wide, drains E.; asc. 10 ft. along E. slope.

19.20 Road, bears NE. and W.; asc. E. slope.

29.70 Wash, 3 ft. deep, 50 lks. wide, drains E.

37.48 Point for the $\frac{1}{4}$ sec. cor. of secs. 33 and 34.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 6 ins. in the ground to bedrock, in a mound of stone, $3\frac{1}{2}$ ft. base to top, with brass cap mkd.

T17S R63E

S33 | S34

1958

Cont. along E. slope.

43.70 Wash, 4 ft. deep, 30 lks. wide, drains NE.; asc. 10 ft. over SE. slope.

59.50 Wash, 3 ft. deep, 30 lks. wide, drains NE.; asc. 200 ft. over rocky SE. slope.

77.30 Point selected for the witness cor. of secs. 27, 28, 33 and 34.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., over a cross (X) cut on solid rock, in a mound of stone, 4 ft. base to top, with brass cap mkd.

T17S R63E

W C

S28 | S27

S33 | S34

1958