

## Independent Resurvey of the Subdivision of T. 17 S., R. 63 E.

## Chains

Set an iron post, 30 ins. long, 2½ ins. diam., 6 ins. in the ground to bedrock, in a mound of stone, 4 ft. base to top, with brass cap mkd.

T16S R63E

S33

S 9 | S10

WCC

T17S R63E

1958

From the true point for the closing cor. the standard cor. of secs. 32 and 33, T. 16 S., R. 63 E. bears W. 15.74 chs. dist., an iron post set, mkd. and witnessed as described in the official record.

From the same point the standard ¼ sec. cor. of sec. 33, T. 16 S., R. 63 E., bears E. 24.26 chs. dist., an iron post, set, mkd. and witnessed as described in the official record.

Land, broken.

Soil, rocky and gravelly.

Timber, none.

Undergrowth, creosote bush.

At midpoint bet. the closing cor. of secs. 10 and 11, and the true point for the closing cor. of secs. 9 and 10, T. 17 S., R. 63 E.

Set an iron post, 30 ins. long, 2½ ins. diam., 8 ins. in the ground to bedrock, in a mound of stone, 3 ft. base to top, with brass cap mkd.

¼ S10

T17S R63E

1958

From this cor. the standard ¼ sec. cor. on the S. bdy. of sec. 33, T. 16 S., R. 63 E., bears W. 15.87 chs. dist., an iron post, 1 in. diam., set, mkd. and witnessed as described in the official record.

The ¼ sec. cor. on the N. bdy. of sec. 4, T. 18 S., R. 63 E., an iron post, 1 in. diam., set, mkd. and witnessed as described in the official record was remarked in accordance with the special instructions.

T17S R63E

¼ S33

S 4

T18S

1958

From the closing cor. of secs. 4 and 5, T. 18 S., R. 63 E., an iron post, 3 ins. diam., set, mkd. and witnessed as described in the official record. In accordance with the special instructions this cor. was remarked.

T17S R63E

S32 | S33

S5 | S4

T18S

1958