

## Dependent Resurvey, S. Bdy., T. 38 N., R. 32 E.

Chains

T38N R32E

$$\frac{S31}{S6}$$
T37N  
1959

- 47.55 Dry wash, 10 lks. wide, 1 ft. deep, drains N. 20° E.
- 53.55 Dry wash, 40 lks. wide, 3 ft. deep, drains N. 15° E.
- 80.00 Dry wash, 20 lks. wide, 3 ft. deep, drains N. 50° E.
- 80.66 The cor. of Tps. 37 and 38 N., Rs. 31 and 32 E., is monumented by the remains of old rotten post with 6 faint grooves on 4 sides, and 4 faint pits; also fits topography from old record.

At the cor. point.

Set an iron post, 30 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.

$$\begin{array}{c} T38N \\ R31E \mid R32E \\ S36 \mid S31 \\ S1 \mid S6 \\ T37N \\ 1959 \end{array}$$

Land, gradual E. slope.

Soil, sandy loam.

Vegetation, sagebrush and shadscale.

## Dependent Resurvey of the West Boundary of T. 38 N., R. 32 E.

Reestablishment of the survey by G. W. Garside in 1874.

N. 0° 58' E., bet. secs. 31 and 36.

Over gradual E. slope, through sagebrush and shadscale.

- 4.10 Dry wash, 15 lks. wide, 1 ft. deep, drains N. 55° E.
- 13.70 Dry wash, 10 lks. wide, 1 ft. deep, drains N. 40° E.
- 18.60 Dry wash, 10 lks. wide, 1 ft. deep, drains E.
- 40.67 The ½ sec. cor. of secs. 31 and 36 at proportionate dist., there is no remaining evidence of the original cor.

Set an iron post, 30 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.

$$\begin{array}{c} T38N \\ R31E \mid R32E \\ S36 \mid S31 \\ 1959 \end{array}$$

- 44.45 Dry wash, 10 lks. wide, 1 ft. deep, drains N. 53° E.
- 49.95 Dry wash, 10 lks. wide, 3 ft. deep, drains N. 55° E.
- 81.34 The cor. of secs. 25, 30, 31 and 36 at proportionate dist.; there is no remaining evidence of the original cor.