

## Survey, Portion of Subdivisional Line, T. 29 N., R. 43 E.

Chains

as described in the official record.

I change the marks on the brass cap to read  $\frac{1}{4}$  S.15, 1914.

---

General Description

The land within the portion of T. 29 N., R. 43 E., which was surveyed, is nearly level, except for rolling hills along the west tier of sections. The drainage is northeasterly in the valley, and easterly on the hills. The main channel is the Reese River, which enters approximately 11 chains east of the southwest corner of section 35, continuing northerly to approximately 2 chains east of the northwest corner of section 23. The elevation varies from about 4,700 ft. on the valley to 5,500 ft. on the hills.

The soil is loam in the valley and gravel and rocks on the hills, with undergrowth of sagebrush and shadscale.

There are two gravel roads in this portion of the township. One enters near S.  $\frac{1}{4}$  corner at section 32 and leaves near E.  $\frac{1}{4}$  cor. of section 24. The other enters near the southeast corner of section 31, bearing northerly to where it passes about 10 chains east of the northwest corner of section 17.

There is considerable homestead activity in this township - almost the whole valley has been covered by homestead entries, in the last year.

There are no apparent mineral deposits within the township.