

Dependent Resurvey, Portion of Subdivisional Lines, T. 25 N., R. 40 E.

Chains	
	Over rolling land; asc. 80 ft. over E. slope.
19.00	Head of small wash, drains SE.; asc. 100 ft. over E. slope.
33.80	Small spur, bears SE.; thence along S. slope.
39.60	Wash, 20 lks. wide, 2 ft. deep, drains SE.; enter scattered juniper, bears SE and NW.
40.14	Point for the $\frac{1}{4}$ sec. cor. of secs. 29 and 32, at proportionate dist.; there is no remaining evidence of the original cor.
	At the cor. point
	Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.
	T25N R40E $\frac{1}{4}$ $\frac{S29}{S32}$ 1960
	No available accessories.
	Asc. 350 ft. over NE. slope of spur.
72.80	Spur, bears S. 85° E.; asc. 60 ft. along S. slope of spur.
80.28	The cor. of secs. 29, 30, 31 and 32.
	Land, rolling 40 chs., low mountainous 40.00 chs. Soil, gravelly sandy clay. Timber, none. 40 chs., scattered juniper 40.00 chs. Undergrowth, shadscale.

GENERAL DESCRIPTION

The land within this township is located on the western side of Antelope Valley. The general elevation varies from 4,900 feet above sea level to 5,900 feet above sea level. The area drains southeasterly into the nearly level desert, except section 3 which drains north-westerly.

The soil varies from light sandy clay on the level land, gravelly sandy clay on the rolling land and sandy clay on the low mountains.

The vegetation is medium growth of shadscale and white sage. The timber is composed of a scattered growth of scrub juniper in section 32 and 33.

There is no water or habitation within the township. Access into the township is provided by numerous desert trail roads.