

Dependent Resurvey of Second Standard Parallel
North along the South Boundary of T. 11 N., R. 43 E.

Chains

- Raise a mound of stone, $3\frac{1}{2}$ ft. base, $2\frac{1}{2}$ ft. high, N. of corner.
- 60.35 Wash, 30 lks. wide, 3 ft. deep, drains NE., continue ascent; ascend 230 ft. over moderately steep ESE. slope to corner.
- 80.71 The cor. of Tps. 10 and 11 N., Rs. 42 and 43 E., monumented with a square post, firmly set, marked and witnessed as described in the official record.

At the corner point

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 10 ins. in the ground and in a mound of stone, 4 ft. base to top, with brass cap mkd.

T11N
R42E R43E
S36 | S31
S 1 | S 6
T10N
1961

Reset the original corner post along side the iron post.

Land, mountainous.

Soil, stony.

Timber, scattered juniper and pinon.

Undergrowth, sagebrush.

Dependent Resurvey of East Boundary - T. 10 N., R. 43 E.

Reestablishment of the Survey Executed by
A. J. Hatch, D. H. Barker, and E. L. Bridges,
Deputy Surveyors, in 1873.

Beginning at the cor. of Tps. 9 and 10 N., Rs. 43 and 44 E., which is monumented with a granite stone, 36x24x16 ins. above ground, firmly set, marked and witnessed as described in the official record.

At the corner point

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.

T 10 N
R43E R44E
S 36 | S 31
S 1 | S 6
T9N
1961

Raise a mound of stone, 4 ft. base, $2\frac{1}{2}$ ft. high, S. of corner.

Bury the original corner stone along side the iron post.

N. $1^{\circ} 14'$ E., along the E. bdy. of sec. 36.

Over gently rolling land, through medium heavy undergrowth.

- 18.30 Wash, 15 lks. wide, 4 ft. deep, drains WNW.
- 25.30 Road, bull-dozed, bears E. and W.
- 38.50 Wash, 20 lks. wide, 2 ft. deep, drains W.

40.245 Point for the $\frac{1}{4}$ sec. cor. of secs. 31 and 36, at proportionate distance; there is no remaining evidence of the original corner.