

Dependent Resurvey of East Boundary, T. 10 N., R. 43 E.

Chains

T 10 N  
R43E R44E  
S 1  $\frac{1}{2}$  S 6  
1961

Raise a mound of stone, 4 ft. base, 2½ ft. high, W. of cor.  
Reset the original corner stone, alongside the iron post.

N. 0° 17' E., beginning new measurement.  
Continue over undulating land, through heavy undergrowth.

27.70 Wash, 30 lks. wide, 4 ft. deep, drains WNW.

39.98 Intersect the Second Standard Parallel North.

The closing cor. of Ts. 10 N., Rs. 43 and 44 E., monumented with  
and iron post, 3 ins. diam., firmly set, marked and witnessed  
as described in the official record.  
  
Land, undulating.  
Soil, sandy and gravelly clay loam.  
Timber, none.  
Undergrowth, sagebrush and creosote bush.

Dependent Resurvey of the South Boundary, T. 10 N., R. 43 E.  
  
Reestablishment of the Survey Executed by A. J. Hatch,  
D. H. Barker and E. L. Bridges, Deputy Surveyors,  
in 1873

From the cor. of Tps. 9 and 10 N., Rs. 43 and 44 E.  
N. 89° 14' W., bet. secs. 1 and 36.  
  
Over nearly level land through medium dense undergrowth, desc. 40  
ft. over gentle SW. slope.

10.90 Graded road, bears N. and S., descend 40 ft. over SW. slope.

20.90 Power and telephone lines, bears S. 17° W. and N. 17° E., descend  
20 ft. over SW. slope.

26.80 Bladed road, bears S. 17° W. and N. 17° E., desc. 50 ft. over  
SW. slope.

39.66 The ¼ sec. cor. of secs. 1 and 36, monumented with a granite stone,  
12x12x8 ins. above ground, firmly set, marked and witnessed as  
described in the official record.

At the corner point  
  
Set an iron post, 30 ins. long, 2½ ins. diam., 24 ins. in the  
ground, with brass cap mkd.

T10N R43E  
¼ S 36  
S 1  
T9N R43E  
1961