

Dependent Resurvey of the Subdivisional Lines, T. 10 N., R. 43 E.

Chains	
15.00	<p>From the cor. of secs. 1, 2, 11 and 12.</p> <p>N. 89° 32' W., bet. secs. 2 and 11.</p> <p>Over undulating land, through heavy undergrowth.</p> <p>Bladed road, bears NW. and SE.</p>
40.05	<p>Point for the $\frac{1}{4}$ sec. cor. of secs. 2 and 11, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set an iron post, 30 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.</p> <p style="text-align: center;">T10N R43E $\frac{1}{4}$ $\frac{S}{S11}$ 1961</p>
80.10	<p>Deposit broken glass, around the iron post, 6 ins. below the surface of the ground.</p> <p>Continue over undulating land, through heavy undergrowth.</p> <p>The corner of secs. 2, 3, 10, and 11.</p> <p>Land, undulating. Soil, sandy and gravelly clay loam. Timber, none. Undergrowth, sagebrush and creosote bush.</p>
39.92	<p>N. 0° 33' W., bet. secs. 2 and 3.</p> <p>Over nearly level land, through heavy undergrowth.</p> <p>Point for the $\frac{1}{4}$ sec. cor. of secs. 2 and 3, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set an iron post, 30 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.</p> <p style="text-align: center;">T10N R43E $\frac{1}{4}$ S 3 S 2 1961</p>
80.62	<p>Deposit broken glass around the iron post, 6 ins. below the surface of the ground.</p> <p>Continue over nearly level land, through heavy undergrowth.</p> <p>Intersect the Second Standard Parallel North.</p> <p>Point for the closing cor. of secs. 2 and 3; a portion of the original corner post, badly decayed was found lying loose on the ground.</p> <p>Set an iron post, 30 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.</p> <p style="text-align: center;">T11N R43E $\frac{1}{4}$ S 3 S 2 C C T10N R43E 1961</p>