

## Dependent Resurvey of the East Boundary of T. 6 N., R. 40 E.

Chains

T6N  
R40E R41E  
 $\frac{1}{4}$   
S1|S6  
1959

Deposit broken glass alongside iron post.

Raise a mound of stone, W. of cor.

79.82

The cor. of Tps. 6 and 7 N., Rs. 40 and 41 E., secs. 1, 6, 31 and 36, determined from the remains of the original wood post (decayed) and set in a mound of earth.

At the cor. point

Set an iron post, 30 ins. long,  $2\frac{1}{2}$  ins. diam., 24 ins. in the ground with brass cap mkd.

T7N  
R40E R41E  
S36|S31  
S1|S6  
T6N  
1959

Deposit remains of original wood post alongside iron post.

Deposit broken glass alongside iron post.

Raise a mound of stone S. of cor.

Land, nearly level.

Soil, sandy loam.

Timber, none.

Undergrowth, desert vegetation.

---

Dependent Resurvey of First Standard Parallel North, through  
R. 40 E.

---

Reestablishment of the survey executed by Glover and Perrin,  
Deputy surveyors in 1880.

From the cor. of Tps. 6 N., Rs. 40 and 41 E., secs. 31 and 36.

N.  $89^{\circ} 25'$  W., along the S. bdy. of sec. 36.

Over nearly level land, through desert vegetation.

39.86

The standard  $\frac{1}{4}$  sec. cor. of sec. 36, determined from the remains of the original wood post (decayed) and set in a mound of earth.

At the cor. point

Set an iron post, 30 ins. long,  $2\frac{1}{2}$  ins. diam., 22 ins. in the ground, with brass cap mkd.

T6N R40E  
S C  
 $\frac{1}{4}$  S36  
1959

Deposit remains of original wood post alongside iron post.

Deposit broken glass alongside iron post.

Raise a mound of stone N. of cor.