

## Survey of a Portion of the Subdivisional Lines - Tp. 3 S., R. 61 E.

Chains									
31.50	Top of ascent, slopes NW., begin descent; desc. 230 ft. over W. slope.								
40.04	<p data-bbox="331 451 1449 486">Point for the <math>\frac{1}{4}</math> sec. cor. of secs. 19 and 30.</p> <p data-bbox="331 513 1449 585">Set an iron post, 30 ins. long, <math>2\frac{1}{2}</math> ins. diam., 6 ins. in the ground, to solid rock, and in a mound of stone to top, with brass cap mkd.</p> <div data-bbox="786 620 922 747" style="text-align: center;"> <p>T3S R61E</p> <table border="0"> <tr> <td><math>\frac{1}{4}</math></td> <td>S 19</td> </tr> <tr> <td></td> <td>S 30</td> </tr> <tr> <td></td> <td>1961</td> </tr> </table> </div>	$\frac{1}{4}$	S 19		S 30		1961		
$\frac{1}{4}$	S 19								
	S 30								
	1961								
	Continue descent over rough mountainous land; desc. 305 ft. over steep rocky, W. slope.								
51.30	Hillside draw, drains NW., continue descent; desc. 72 ft., over NW. slope.								
57.60	Top of spur, slopes NW., desc. 263 ft. over steep, rocky WSW. slope.								
73.50	Wash, 1 chain wide, 12 ins. deep, drains NW., desc. 40 ft. over gradual W. slope.								
80.08	<p data-bbox="331 1150 1449 1311">The cor. of secs. 24 and 25 only, on the East boundary of T. 3 S., R. 60 E., which is monumented with an iron post, <math>2\frac{1}{2}</math> ins. diam., firmly set in the ground, marked and witnessed as described in the official record. This corner will now serve as a corner of maximum control, I alter the markings on the brass cap to read:</p> <div data-bbox="754 1346 906 1507" style="text-align: center;"> <p>T3S</p> <table border="0"> <tr> <td>R60E</td> <td>R61E</td> </tr> <tr> <td>S 24</td> <td>S 19</td> </tr> <tr> <td>S 25</td> <td>S 30</td> </tr> <tr> <td></td> <td>1961</td> </tr> </table> </div>	R60E	R61E	S 24	S 19	S 25	S 30		1961
R60E	R61E								
S 24	S 19								
S 25	S 30								
	1961								
	<p data-bbox="331 1534 1449 1666">Land, heavily rolling mountainous. Soil, sandy and gravelly, stony. Timber, none. Undergrowth, cactus and sagebrush.</p>								

---

General Description

---

The land in the area surveyed varies from nearly level on the western portion of the area, to gently rolling through the middle area and rough and broken mountainous on the eastern portion of the area. The soil in the western half of the area is a sandy clay loam, and in the eastern half the soil is sandy and gravelly, stony. There is a graded graveled road that enters sec. 18, approximately 20 chs. North of the cor. of secs. 13, 18, 19, and 24, on the W. bdy. of the section which traverses in a general ENE. direction, and leaves the section near the cor. of secs. 7, 8, 17, and 18, on the N. bdy. of the section.

There are no developments or settlers in the area surveyed. There is no running water in the area. There is no timber but fair growth of native grasses along the water courses throughout the area.