

295

Remonumentation of Corners, T. 12 N., R. 42 E., M.D. Mer.

Chains

Located on W. side Big Smoky Valley, slight NE. slope, and approx. $\frac{1}{2}$ mile S. of S. Twin Rivers, draining NE.

At the cor. of secs. 2, 3, 10, and 11, T. 12 N., R. 42 E., which is a granite stone, 21x12x7 ins., loosely set in small mound of stone, marked with 5 notches on S. and 2 notches on E. edge. No other accessories.

At cor. point

Set an iron post, 30 ins. long, 2 $\frac{1}{2}$ ins. diam., 24 ins. in the ground, over broken glass, with orig. cor. stone buried on N. side; brass cap marked

T12N R42E	
S 3	S 2
S10	S11
1961	

Raise a mound of stone, 3x2 ft., W. of cor.

Remonumentation of Corners, HES No. 44,
in T. 10 N., R. 42 E. (Unsurveyed)

Homestead Entry Survey No. 44, located in sec. 25, T. 10 N., R. 42 E., (unsurveyed), M. D. Mer., Nevada, was surveyed in 1913 by John C. Brown, Forest Ranger.

The following field notes are those of a remonumentation of identified original corners on HES No. 44, in unsurveyed sec. 25, T. 10 N., R. 42 E., M.D. Mer., Nevada. The position of each corner was marked by the original monument, or determined from corner accessories recorded in the official survey record.

The corners remonumented were selected by the Forest Service as being adjacent to, or controlling the boundaries of Forest Service Lands. The remonumentation was requested by and accomplished in cooperation with the Forest Service.

At cor. No. 1, HES No. 44, monumented by a diorite stone, 25x12x9 ins. firmly set, marked 1 HES 44 on side facing claim, and a X on top (which I destroyed) witnessed by a scattered mound of stone, SW. of cor. There is no remaining evidence of the 2 bearing posts.

At cor. point

Set an iron post, 30 ins. long, 2 $\frac{1}{2}$ ins. diam., 24 ins. in the ground, with orig. cor. stone buried on SW. side of post; brass cap marked

1	
HES	1
44	
1961	

Place a collar of rock around post.

A cedar post, 10 ins. diam., 8 ft. long, and firmly set, bears S. 74° W., 24 lks. dist.