

Remonumentation of Corners, HES No. 125, in
T. 10 N., R. 40 E. (Unsurveyed)

Chains

At cor. No. 5, HES No. 125, on the S. bdy. of sec. 32, T. 11 N., R. 40 E., monumented by a granite stone, 25x11x7 ins., firmly set, marked 5 HES 125, on side facing claim, and CC on S. side; unwitnessed.

At cor. point

Set an iron post, 30 ins. long, 2½ ins. diam., 24 ins. in the ground, over broken glass, with orig. cor. stone buried on E. side of post; brass cap marked

5
HES
125

1961.

Place collar of rock around post.

Corner is located under wire fence, bears E., and extends W. about 1.30 chs. dist. to cor., thence N.

Remonumentation of Corners, HES no. 139,
in T. 10 N., R. 40 E. (Unsurveyed)

Homestead Entry Survey No. 139, located in unsurveyed sec. 29, T. 10 N., R. 40 E., Mount Diablo Meridian, Nevada, was surveyed by F. C. Haman, Forest Ranger, in 1917.

The following field notes are those of the remonumentation of identified original corners on Homestead Entry Survey No. 139, situated in T. 10 N., R. 40 E., Mount Diablo Meridian, Nevada. (Unsurveyed). The corners remonumented were selected by the Forest Service as being adjacent to, or controlling the boundaries of Forest Service Lands. The remonumentation was requested by and accomplished in cooperation with the Forest Service.

HES No. 139, in T. 10 N., R. 40 E.

At cor. No. 1, HES No. 139, which is monumented with a granite stone, 24x12x10 ins., firmly set, marked with 1 HES 139 on SW. face, witnessed by a mound of stone within claim and 1 bearing rock as described in the official record.

At cor. point

Set an iron post, 30 ins. long, 2½ ins. diam., 24 ins. in the ground, over broken glass, and with the orig. cor. stone buried on the W. side of post; brass cap marked

1
HES 139

1961

Place collar of rock around, and rebuild mound of stone.