Remonumentation of Corners, T. 17 N., R. 44 E., M.D. Mer.

Chains

354

Corner is located about 40 lks. E. from road bearing NE. and SW., and about 8 chs. dist., S. of Birch Creek, drains easterly.

At the cor. of sec. 1 and 2, on N. bdy. of T. 17 N., R. 44 E., which is a granite stone, 24x9x4 ins., marked with 1 notch on E. and 5 notches on W. edge, firmly set in the ground, and witnessed by a small mound of stone, S. of cor.

At the cor. point

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 18 ins. in the ground to bedrock, over broken glass; orig. cor. stone set on S. of post; brass cap mkd.

Raise a mound of stone around post to top.

Corner is located on slight SE. slope on W. side of Smoky Valley, and approximately $1\frac{1}{2}$ chs. N. of road to Birch Canyon, bearing nearly N. 80° W. and S. 80° E.

At the $\frac{1}{4}$ sec. cor. on N. bdy., sec. 1, T. 17 N., R. 44 E., which is a granite stone, 18x14x8 ins., marked $\frac{1}{4}$ on N. face, firmly set in the ground, and witnessed by 2 stones.

At the cor. point

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, over broken glass; orig. cor. stone buried on S. side of post with brass cap mkd.

Place collar of rock around post.

The $\frac{1}{4}$ sec. cor. on S. bdy., sec. 36, T. 18 N., bears E. 2.22 $\frac{1}{2}$ chs. dist.

At the cor. of Ts. 17 N., Rs. 44 and 45 E., which is a granite stone, $18 \times 10 \times 9$ ins., marked with 6 notches on S. and W. sides, and 6 grooves on E. face; witnessed by evidence of pits to E. and W., and mound of earth and stone, S. of cor.

At the cor. point

Set an iron post, 30 ins. long $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, over broken glass, with original cor. stone, buried on S. side of post; brass cap mkd.

T18N R44E

S36
S 1 S 6
R44E R45E
T17N
1961