Remonumentation of Corners, T. 19 N., R. 43 E., M.D. Mer.

## Chains

Marked with a granite stone, 11x10x9 ins., marked with 2 grooves on S and 3 grooves on N. face; loosely set, and witnessed by a small mound of stone, on E. side of cor.

At the cor. point

Set an iron post, 30 ins. long,  $2\frac{1}{2}$  ins. diam., 20 ins. in the ground to rock, over broken glass, with original cor. stone buried on E. side of post; brass cap mkd.

Raise a mound of stone to top, around post.

Remonumentation of Corners, T. 19 N., R. 44 E., M.D. Mer.

A portion of the west boundary of T. 19 N., R. 44 E., M.D. Mer. was surveyed by Tracy in 1867. Portions of the north, south and east boundaries and subdivisional lines were surveyed by Barker and Skinner in 1875. The north boundary was completed by Gurner in 1905. Thurtell and Kearney completed the survey of the boundaries and subdivisional lines in 1909 and resurveyed portions of the south and west boundaries and subdivisional lines.

The following field notes are those of the remonumentation of certain identified original corners in T. 19 N., R. 44 E., Mt. Diablo Mer., Nevada. The position of each corner was marked by the original monument, or determined from corner accessories recorded in the original survey record.

The corners remonumented were selected by the U. S. Forest Service as being adjacent to, or controlling the boundaries of Forest Service lands. The remonumentation was requested by and accomplished in cooperation with the Forest Service.

T. 19 N., R. 44 E., M.D. Mer. Nevada

At the  $\frac{1}{4}$  sec. cor. of secs. 20 and 29, T. 19 N., R. 44 E., which is a granite stone,  $27 \times 12 \times 11$  ins., marked  $\frac{1}{4}$  on N. face, firmly set in the ground; unwitnessed.

At the cor. point

Set an iron post, 30 ins. long,  $2\frac{1}{2}$  ins. diam., 24 ins. in the ground, over glass deposit, and with original cor. stone buried on N. side of post; brass cap mkd.

Place collar of rock around post.

Corner is located on gentle SW. slope in tall sagebrush, about 35 lks. E. of wash in a main draw, draining SW., and approximately 5 chs. dist. S. of U.S. Highway No. 50.