

Remonumentation of Corners, T. 12 N., R. 44 E.

Chains

The west boundary, portions of the south and north boundaries, and subdivisional lines of T. 12 N., R. 44 E., M.D. Mer., Nevada, were surveyed by Hatch, Barker, and Bridges in 1873. In 1905, Clinton Gurner completed the survey of the boundaries and subdivisional lines and resurveyed portions of the boundaries and subdivisional lines.

The following field notes are those of the remonumentation of certain identified original corners in T. 12 N., R. 44 E., M.D. Mer., Nevada. The position of each corner was marked by the original monument.

The corners remonumented were selected by the Forest Service as being adjacent to, or controlling the boundaries of Forest Service lands. The remonumentation was requested by and accomplished in cooperation with the Forest Service.

T. 12 N., R. 44 E., M.D. Mer.

At the cor. of secs. 34 and 35, on S. bdy. of T. 12 N., R. 44 E., monumented by a granite stone, 19x14x8 ins., firmly set, mkd. with 2 notches on E. and 4 notches on W. edge; witnessed by a small mound of stone, W. of cor.

At the cor. point

Set an iron post, 30 ins. long, 2½ ins. diam., 24 ins. in the ground, over broken glass deposit; original corner stone buried on N. side of post; brass cap marked

T12N R44E
S34|S35
S3
T11N
1961

Place collar of rock, around post, and enlarge the mound of stone.

At the ¼ sec. cor. of secs. 34 and 35, marked by andesite stone, 26x7x6 ins., firmly set, marked with ¼ on W. face; witnessed by a mound of stone, 2x1½ ft., NW. of cor.

At cor. point

Set an iron post, 30 ins. long, 2½ ins. diam., 20 ins. in the ground, to rock, over broken glass; original corner stone buried on E. side of post; brass cap marked

¼
T12N R44E
S34|S35
1961

Raise a large mound of stone around post.

Cor. is located on a NE. slope, 25 lks. dist. S. of wash, drains NW.
