

## Remonumentation of Corners on HES No. 97, in T.10N., R.44 E.

## Chains

Homestead Entry Survey No. 97, located in secs. 2 and 11, T. 10 N., R. 44 E., M.D. Meridian, Nevada, was surveyed by R. D. Garver, Forest Examiner, in 1915.

The following field notes are those of a remonumentation of identified original corners on HES No. 97, in secs. 2 and 11, T. 10 N., R. 44 E., M. D. Mer. The position of each corner was marked by the original monument, or determined from corner accessories recorded in the official survey record.

The corners remonumented were selected by the Forest Service as being adjacent to, or controlling the boundaries of Forest Service Lands. The remonumentation was requested by and accomplished in cooperation with the Forest Service.

## Homestead Entry Survey No. 97

At cor. No. 1, HES No. 97, monumented by a granite stone, 27x10x8 ins., firmly set, over broken glass, marked 1 HES 97 on side facing claim, and witnessed by a mound of stone, and 2 bearing rocks.

A granite boulder, 6x7x4 ft. mkd. X 1 HES 97 BR, bears N. 89° 20' E., 148 lks. dist.

A granite outcrop, 8x3x2 ft., mkd. X 1 HES 97 BR, bears N. 30° 10' E., 25 lks. dist (record 24 lks. dist.).

At cor. point

Set an iron post, 30 ins. long, 2½ ins. diam., 24 ins. in the ground, over broken glass, with orig. cor. stone buried on NE. side of post; brass cap marked

1961

Place collar of rock around post, and rebuild the mound of stone to the NE.

At cor. No. 2, HES No. 97, monumented by a red granite stone, 22x13x7 ins., firmly set in a mound of stone on bedrock, over glass, marked 2 HES 97 on side facing claim. I was unable to identify the two bearing rocks as recorded in official record.

At cor. point

Set an iron post, 30 ins. long, 2½ in. diam., 6 ins. in rock, over broken glass, and supported in a mound of stone, 5 ft. base to top; brass cap marked

1961