

Remonumentation of Corners on HES No. 97,
in T. 10 N., R. 44 E.

Chains

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 6 ins. in ground to solid rock, over broken glass, and supported in a mound of stone, 6 ft. base, to top of post; brass cap marked

HES
97 8

1961

Corner is located on a rock W. slope, about $2\frac{1}{2}$ chs. dist. E. of bottom land.

Remonumentation of Corners on HES No. 145, in T.12N., R45E.

Homestead Entry Survey No. 145, located in unsurveyed sec. 31, T. 12 N., R. 45 E., M.D. Mer., Nevada, was surveyed by F. C. Haman, Forest Ranger, in 1917.

The following field notes are those of a remonumentation of identified original corners on HES No. 145, in sec. 5, T. 12 N., R. 45 E., M.D. Mer. The position of each corner was marked by the original monument.

The corners remonumented were selected by the Forest Service as being adjacent to, or controlling the boundaries of Forest Service lands. The remonumentation was requested by and accomplished in cooperation with the Forest Service.

Homestead Entry Survey No. 145

At cor. No. 1 HES No. 145, on line bet. secs. 31 and 36, on E. bdy. T. 12 N., R. 44 E., which is marked by granite stone, 27x9x7 ins., firmly set, mkd. with a X on top (destroyed), 1 HES 145 on side facing claim, and CC on SE. side; from which

A malapai stone, showing 1x1x1 ft., mkd. X 1 HES 145 BR, bears S. $76^{\circ}23'E.$, 46 lks. dist.

A malapai stone, showing $2x1\frac{1}{2}x1\frac{1}{2}$ ft., mkd. X 1 HES 145 BR, bears N. $4^{\circ}42'E.$, 31 lks. dist.

And witnessed by a mound of stone, 3 x 2 ft. to NE.

At cor. point

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 20 ins. in the ground to rock, over broken glass, with original corner stone set along W. side of post; brass cap marked

HES
1 145

1961

Raise a mound of stone around post.

From this cor. the $\frac{1}{4}$ sec. cor. of secs. 31 and 36, on E. bdy. of T. 12 N., R. 44 E.; (by record bearing and dist.) bears S. $0^{\circ}01'W.$, 1.26 chs. dist.