

Remonumentation of Corners on HES No. 145, in
T. 12 N., R. 45 E.

Chains

And witnessed by a mound of stone, 3x2 ft., to the NW.

At cor. point

Set an iron post, 30 ins. long, 2½ ins. diam., 20 ins. in the ground to rock, over broken glass, with orig. cor. stone buried on NE. side of post; brass cap marked

HES
145
4
1961

Raise a mound of stone around post.

Remonumentation of Corners on HES No. 101,
in T. 11 N., R. 44 E.

Homestead Entry Survey No. 101, located in T. 11 N., R. 44 E., M.D. Mer., was surveyed by R. D. Garver, Forest Examiner, in 1915.

The following field notes are those of a remonumentation of certain identified original corners on HES No. 101, in T. 11 N., R. 44 E., M. D. Mer., Nevada. The position of each corner was marked by the original monument.

The corners remonumented were selected by the Forest Service as being adjacent to, or controlling the boundaries of Forest Service Lands. The remonumentation was requested by and accomplished in cooperation with the Forest Service.

Homestead Entry Survey No. 101

At cor. No. 1 HES No. 101, monumented by a granite stone, 25x8x6 ins., firmly set, mkd. 1 HES 101 on side facing claim, and X on top (which I destroyed), witnessed by a scattered mound of stone, and two bearing rocks as described in official record.

At cor. point

Set an iron post, 30 ins. long, 2½ ins. diam., 24 ins. in the ground, over broken glass, orig. cor. stone buried on N. side of post; brass cap marked

HES 101
1
1961

Place collar of rock around post, and rebuild the mound of stone.

From this cor. the record bearing and distance to the cor. of secs. 33 and 34, on S. bdy. T. 11 N., R. 44 E., is S. 43° 23' W., 113.22 chs.