

Remonumentation of Corners on HES No. 101, in  
T. 11 N., R. 44 E.

Chains

At cor. No. 5, HES No. 101, monumented by a malapai rock, 26x9x9 ins., firmly set, marked 5 HES 101 on side facing claim, and a X on top, (destroyed) and witnessed by

A pinon, 18 in. diam., marked X 5 HES 101 BT, bears N. 45° 23' E., 207 lks. dist.

A granite boulder in place, 2 x 3 x 1½ ft. high, marked X 5 HES 101 BR, bears S. 40° 45' W., 88 lks. dist.

At cor. point

Set an iron post, 30 ins. long, 2½ ins. diam., 18 ins. in the ground to rock, over broken glass, with orig. cor. stone set on N. side of post; brass cap marked

HES  
5  
101  
1961

Raise a mound of stone, 4 ft. base, around post.

At cor. No. 6, HES No. 101, monumented by a pinon stump, 10 in. diam. which has been cut off 3½ ft. above ground, scribed 6 HES 101 on side facing claim; from which

A pinon, 12 in. diam., scribed X 6 HES 101 BT, bears S. 55½° E., 33 lks. dist. (record dist. 34 lks.)

A pinon, 12 in. diam., mkd. X 6 HES 101 BT bears S. 58½° W., 9 lks. dist.

Also witnessed by a mound of stone to NW.

I removed the corner stump, and at exact point

Set an iron post, 30 ins. long, 2½ ins. diam., 24 ins. in the ground, over broken glass; brass cap marked

HES  
101 6  
1961

Place collar of rock around post.

Remonumentation of Corners on HES No. 176, in  
T. 11 N., R. 44 E.

Homestead Entry Survey No. 176, located in sec. 22, T. 11 N., R. 44 E., M.D. Mer., Nevada, was surveyed by F. C. Haman, Forest Ranger, in 1917.

The following field notes are those of a remonumentation of identified original corners on HES No. 176, and the ¼ sec. cor. of secs. 15 and 22, in T. 11 N., R. 44 E., M. D. Mer. The position of each corner was marked by the original cor.

The corners remonumented were selected by the Forest Service as being adjacent to, or controlling the boundaries of Forest Service Lands. The remonumentation was requested by and accomplished in cooperation with the Forest Service.