

Remonumentation of Corners on HES No. 176, in
T. 11 N., R. 44 E.

Chains

At cor. point.

Set an iron post, 30 ins. long, 2½ in. diam., 24 ins. in the ground, over broken glass; orig. cor. stone buried on S. side of post; brass cap marked

T11N R44E
¼ $\frac{S15}{S22}$
1961

Place collar of rock around, and enlarge mound of stone, W. of cor.

Cor. is located on gentle W. slope, about ½ ch. dist. S. of unimproved road, bearing nearly E. and W.

Remonumentation of Corners on HES No. 219, in
T. 10 N., R. 45 E.

Homestead Entry Survey No. 219, located in unsurveyed secs. 35 and 36, T. 10 N., R. 45 E., M.D. Mer., Nevada, was surveyed by F. C. Haman, Forest Ranger, in 1917.

The following field notes are those of a remonumentation of identified original corners on HES No. 219, in unsurveyed secs. 35 and 36, T. 10 N., R. 45 E., M.D. Mer. The position of each corner was marked by the original monument.

The corners remonumented were selected by the Forest Service as being adjacent to, or controlling the boundaries of the Forest Service Lands. The remonumentation was requested by and accomplished in cooperation with the Forest Service.

Homestead Entry Survey No. 219

At cor. No. 2 HES No. 219, which is mkd. by a granite stone, 18x9x8 ins., firmly set, mkd. with 2 HES 219 on side facing claim; from which

A mahogany, 10 in. diam., bears S. 23° 26' E., 36 lks. dist.

A pinon, 14 in. diam., bears N. 10° 45' W., 52 lks. dist.

Both trees marked X 2 HES 219 BT.

And witnessed by few scattered rock.

At cor. point

Set an iron post, 30 ins. long, 2½ in. diam., 8 ins. in the ground to rock, over broken glass and X rock, with orig. cor. stone set alongside of post; supported in a mound of stone to top; brass cap marked