

390

Remonumentation of Corners on HES No. 219,
in T. 10 N., R. 45 E.

Chains

A granite rock in place, 4x3x3 ft., bears N. 1° 55' W.,
35 lks. dist. Both marked X 5 HES 219 BR

And witnessed by a small mound of stone.

At cor. point

Set an iron post, 30 ins. long, 2½ in. diam., 24 ins. in the ground,
over a X rock, 6x4x4 ins.; orig. cor. stone is placed along SE. side
of post; brass cap marked

5
HES219

1961

Place collar of rock around post, and rebuild the mound of stone.

At cor. No. 6 HES No. 219, on N. bdy. of sec. 1, T. 9 N., R. 45 E.,
which is a rhyolite stone, 22x8x6 ins., firmly set, mkd. with a X on
top (destroyed), 6 HES 219 and CC facing claim; from which

A cedar stump, 14 in. diam., marked X 6 HES 219 CC BT,
bears N. 38° 48' E., 87 lks. dist.

A granite rock in place, 4x4x3½ ft., mkd. X 6 HES 219 BR,
bears N. 1° 55' W., S. 3° 40' E., 99 lks. dist.

And witnessed by a mound of stone, 3x2 ft. NW. of cor.

At cor. point

Set an iron post, 30 ins. long, 2½ in. diam., 24 ins. in the ground,
over broken glass; orig. cor. stone buried on SW. side of post; brass
cap marked

HES
219 6 cc
1961

Raise a mound of stone, around cor.

Corner is located on rocky SW. slope, about 1 ch. dist NE. of bottom
land along Meadow Creek.

Note: Corner No. 1 of this claim was not remonumented.