Dependent Resurvey of the Subdivisional Lines of T. 36 N., R. 56 E

		Dependent Resurvey of the Subdivisional Lines of T. 36 N., R. 56 E.	
	Chains		
	79.74	The cor. of secs. 1, 6, 7 and 12 on the W. bdy. of the township.	
		Land, mountainous Soil, sandy loam and granite outcroppings. Timber, none. Undergrowth, sagebrush and shadscale.	226
		N. 0° 57' E., bet. secs. 5 and 6.	
		Over rolling land.	
	7.10	Wire fence, bears NW. and SE.	
	41.99	Point for the 1/2 sec. cor. of secs. 5 and 6, at proportionate distance; there is no remaining evidence of the original corner.	
		Set an iron post 28 ins. long, 2½ ins. diam., 22 ins. in the ground and in a collar of stone, with brass cap mkd.	
		T36N ₁ R56E S6 S5	
		1961	
	50.50	Wash, 20 1ks. wide, 3 ft. deep, drains E.	1-0.
	51.50	Trail road, bears E. and W.	
	62.99	Point for the N. 1/16 sec. cor. of secs. 5 and 6.	
		Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 20 ins. in the ground and in a collar of stone, with brass cap mkd.	
		T36N R56E	
	1 1 1	N1/16 S6 S5 1961	
	84.49	The cor. of secs. 5, 6, 31 and 32 on the N. bdy. of the township.	
		Land, rolling. Soil, sandy loam.	
		Timber, none.	
		Undergrowth, sagebrush and shadscale.	
	2	General Description	
		The township is located about 8 miles NE. of Elko, Nevada. The land consists mostly of rolling desert with the extreme west portion reaching the barren foothills. The soil consists mostly of a sandy loam, with a light clay and granite outcroppings in the mountains. There is a scattering growth of cotton wood timber along Jackson	
	e and a	Creek which traverses through the SW. portion of the township. There were no settlers in the area at the time of the resurvey, but section 25 was being developed for homesites. There is a mine near the ½ corner on the S. bdy. of sec. 34, not in operation at the time of the survey. No other minerals were noted during the survey.	
11			
		# 1 as W a W Sa C C C C C C C C C	