Limited Dependent Resurvey, T. 32 S., R. 66 E., M. D. M., Nevada

der cor.
1

General Description

The township is located immediately south of Davis Dam.

The land is a rolling bench descending into the Colorado River. There is a narrow flood plain along secs. 33, 34 and 35. The soil consists of sand and coarse gravel with sandy silt in the river bottom. There is a dense growth of willow, mesquite and arrowweed along the river and a scattering growth of creosote brush and caction the bench.

Nevada State Highway No. 77 traverses through the township near the north boundary thereof. A graded road from Davis Dam to Needles, California traverses through the township, entering on the north boundary of sec. 10 and leaving on the south boundary of sec. 32.

There are ranches in secs. 13 and 28.

There is a gravel pit in the SE. corner of sec. 27, not in operation at the time of the survey. There is no evidence of past or present mining activity or the presence of minerals.