

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FIELD NOTE PAPER

CHAINS

DEPENDENT RESURVEY, NORTH BDY., T. 43 N., R. 31 E.

39.96

N. 89° 48' W., bet. secs. 6 and 31.

Over nearly level land, through medium undergrowth.

The $\frac{1}{4}$ sec. cor. of secs. 6 and 31, monumented with the original unmarked woodpost, 1x1x30 ins. long.

At the corner point

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground and in a collar of stone, with brass cap mkd.

T44N R31E
 $\frac{1}{4}$ $\frac{S \ 31}{S \ 6}$
T43N
1962

Reset the original woodpost, alongside the iron post.

S. 88° 45' W., beginning new measurement.

Over nearly level land.

40.02

The corner of Tps. 43 and 44 N., Rs. 30 and 31 E., monumented with unmarked, original woodpost, 1x1x24 ins. long, with steel fence post set alongside.

At the corner point

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground and in a collar of stone, with brass cap mkd.

T44N
R30E R31E
 $\frac{S \ 36}{S \ 1} \mid \frac{S \ 31}{S \ 6}$
T43N
1962

Reset original woodpost and steel fence post alongside iron post.

From this point the cor. of secs. 1, 2, 35 and 36, Tps. 43 and 44 N., R. 30 E., bears N. 89° 36' W., 79.87 chs. dist., monumented with an iron post, 2 ins. diam., set, mkd. and witnessed as described in the official record.

Land, nearly level.

Soil, sandy clay.

Undergrowth, shadscale, buttonbrush and sagebrush.