

DEPENDENT RESURVEY, T. 13 N., R. 18 E.

Chains

A regulation brass tablet, $3\frac{1}{2}$ in. diam., 3 in. stem, firmly cemented in the top of a granite boulder showing 10 ft. by 5 ft. by 5 ft. high on small rocky islet bears West, 340 lks. dist., with top mkd.

R P
1
S 3
S 10
1939

A regulation brass tablet, $3\frac{1}{2}$ in. diam., 3 in. stem, firmly cemented on the top of a huge granite boulder on the lake shore water line, showing 14 ft. by 10 ft. by 10 ft. high, bears N. $2^{\circ}15'E.$, 346 lks. dist., with top mkd.

R P
2
+
S 3
1939

A yellow pine, 14 ins. diam., bears N. $53-3/4^{\circ}E.$, 83 lks. dist., mkd. T13N R18E S3 MC BT.

A yellow pine, 14 ins. diam., bears S. $65\frac{1}{4}^{\circ}E.$, 133 lks. dist., mkd. T13N R18E S10 MC BT.

Base of flag pole at U.S. Forest Service Lookout station bears S. $9^{\circ}57'W.$

Center of lighthouse at N. end of pier bears S. $35^{\circ}40'W.$

Land, rolling and hilly.

Soil, shallow rocky to coarse sandy loam, 3rd rate.

Undergrowth, manzanita, laurel, bitter brush.

Timber, yellow pine, sugar pine, cedar, balsam fir.

Grazing, poor.

Meanders of Lake Tahoe, in sec. 3.

From the closing cor. of secs. 3 and 34, on N. bdy. of Tp.

Along mean high water mark over rocky shore line.

S. $13^{\circ}45'E.$, 7.40 chs.

S. $29^{\circ}45'W.$, 4.20 chs.

S. $16^{\circ}30'W.$, 8.70 chs.

S. $43^{\circ}15'W.$, 3.60 chs.

S. $62^{\circ}15'W.$, 5.40 chs.

S. $53^{\circ}30'W.$, 4.80 chs. At end of course, NW. cor. of Sky-land Lodge bears S. $57^{\circ}E.$, 175 lks. dist.

N. $75^{\circ}30'W.$, 4.90 chs. At 2.25 chs. on this course, N. side of small frame house bears S., 35 lks. dist.

S. $38^{\circ}45'W.$, 1.60 chs.