

290

Survey of a Portion of the South Boundary of T. 13 N., R. 58 E.

Chains	
63.20	Hillside drain, near its head, course S. 30° W.; desc. 120 ft. over SW. slope.
72.00	Gulch, course N. 80° W. 5.00 chs., thence W.; asc. 20 ft.
75.00	Spur, near its foot, slopes N. 80° W.; desc. 40 ft. over W. slope.
80.00	Point for the cor. of secs. 31 and 32. Set an iron post, 3 ft. long, 2 ins. diam., 27 ins. in the ground, with brass cap mkd. <div style="text-align: center;"> T13N R58E <u>S31 S32</u> 1941 </div> from which A pinon, 5 ins. diam., bears N. 53 3/4° E., 170 lks. dist., mkd. T13N R58E S32 BT. A pinon, 13 ins. diam., bears N. 42 1/2° W., 249 lks. dist., mkd. T13N R58E S31 BT. Land, mountainous. Soil, sandy clay loam, gravelly and rocky. Timber, pinon and juniper; undergrowth, sagebrush, buckbrush and a good growth of grass.
	West, along the S. bdy. of sec. 31. Over mountainous land, through dense timber and undergrowth; desc. gradually.
1.40	Ravine, course S. 60° W.; asc. 10 ft. along S. slope.
15.50	Spur, slopes S. 70° W.; desc. 125 ft. over NW. slope. Timber becomes scattering.
39.70	Head of hillside drain, course S. 70° W.; desc. gradually along S. slope.
40.00	Point for the S. 1/4 sec. cor. of sec. 31. Set an iron post, 3 ft. long, 1 in. diam., 15 ins. in the ground to bedrock and in a mound of stone to top, with brass cap mkd. <div style="text-align: center;"> <u>1/4 S 31</u> 1941 </div> from which A pinon, 9 ins. diam., bears N. 43° E., 56 lks. dist., mkd. 1/4 S31 BT. A pinon, 7 ins. diam., bears N. 25° W., 125 lks. dist., mkd. 1/4 S31 BT.
45.20	Gulch, 75 ft. below 1/4 sec. cor., course N. 80° W.; desc. 25 ft. along N. slope.
49.60	Same gulch, course SW.; asc. 20 ft. over SE. slope.