Chains	
	S. 89° 36' E., bet. secs. 2 and 35.
	Desc. 110 ft. over steep E. slope.
4.00	Foot of descent, across level bottom land.
5.60	Small creek, water 2 lks. wide, 2 ins. deep, course N.
7.40	Unimproved road, bears irregularly N. and S.
14.00	Leave bottom land, asc. 400 ft. over broken mountainous land.
38.95	Proportionate distance,
	Set an iron post, 3 ft. long, 1 in. diam., 10 ins. in the ground, to bedrock and in a mound of stone to top, for ¼ sec. cor., with brass cap mkd.

S 35
¼
S 2
1940

	Asc. 450 ft. over broken mountains.
54.00	Spur, slopes NW.; asc. 100 ft. along broken N. slope.
66.00	Desc. 80 ft. along N. slope.
74.00	Ravine, course NW.; asc. 100 ft. over W. slope.
77.91	Proportionate distance,
	Set an iron post, 3 ft. long, 2 ins. diam., 27 ins. in the ground, for cor. of secs. 1, 2, 35 and 36, with brass cap mkd.

T45N R64E
S35 | S36
S 2 | S 1
T44N
1940

from which

A granite boulder, 4x2x1½ ft. above ground, bears N. 59° E., 8 lks. dist., mkd. XBO.

A granite boulder, 5x6x4 ft. above ground, bears S. 5° E., 11 lks. dist., mkd. XBO.

A granite boulder, 4x12x3 ft. above ground, bears S. 42° W., 29 lks. dist., mkd. XBO.

A granite boulder, 1½x2½x½ ft. above ground bears N. 31¼° W., 34 lks. dist., mkd. XBO.

Land, valley bottom and broken mountainous.
Soil, valley bottom, clay; 2nd rate, mountains, very rocky; 4th rate.
Timber, none.
Undergrowth, sagebrush, service brush.
Grazing, fair.

	S. 89° 36' E., bet. secs. 1 and 36.
	Asc. 120 ft. over broken general W. slope.
20.00	Asc. 160 ft. over more rolling general W. slope.