

Dependent Resurvey of the West Boundary of T. 7 N., R. 60 E.

Chains

Set an iron post, 30 ins. long, 2½ ins. diam., 24 ins. in the ground, with the old stone deposited along E. side, with brass cap mkd.

T8N
R59E R60E
S36|S31
S 1|S 6
T7N
1953

raise a mound of stone, 3 ft. diam., 6 ins. high, around corner. Reset the old quartzite stone alongside the iron post.

Land, hilly.
Soil, rocky.
Timber, scattering juniper; undergrowth, sagebrush.

Dependent Resurvey of the North Boundary of T. 7 N., R. 60 E.

Reestablishment of the Survey Executed By
Monroe and Bateman, Deputy Surveyors, in 1871

Note: Although originally surveyed as a common boundary, the corners along this line will not serve for sections of T. 8 N., R. 60 E. The following corners are therefore marked for sections of T. 7 N., R. 60 E., only.

The cor. of Ts. 7 and 8 N., Rs. 60 and 61 E. is marked by the remains of the original monument, the lower portion of a pine post firmly set in the ground, rotted off at the surface, with scattered fragments of the upper portion scattered on the surface.

At the corner point

Set an iron post, 30 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.

T8N
R60E R61E
S36|S31
S 1|S 6
T7N
1953

Dig a trench, 6 ft. diam., and raise a mound of earth, 4 ft. diam., around corner. Bury the remains of the old pine post alongside the iron post.

From this corner, Riordan's windmill bears N. 59° 47' W.

N. 89° 56' W., along the N. bdy. of sec. 1.

Over level, washed land, through low sagebrush.

40.65

Point for the ¼ sec. cor. of sec. 1, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 30 ins. long, 2 ins. diam., 24 ins. in the ground, with brass cap mkd.

¼ S 1
1953

Dig a trench, 5 ft. diam., and raise a mound of earth, 3 ft. diam., around the corner.