

284

Dependent Resurvey, West Bdy., T. 9 N., R. 61 E.

Chains

Set an iron post, 30 ins. long, 2 ins. diam., 26 ins. in the ground, with brass cap mkd.

 $\frac{1}{4}$ S 7

1953

Dig a trench, 5 ft. diam., and raise a mound of earth, 3 ft. diam., around corner.

From this corner, Sorenson's tank bears N. $48\frac{3}{4}^{\circ}$ E., 4.32 chs. dist.

40.80

Rut road, bears S. 60° W. and N. 60° E.

44.70

Graded road, bears S. 17° W. and N. 17° E.; set a fence post with cruiser tag.

52.20

Graded road, bears S. 45° E. 3 chs. then S., and N. 45° W. 3 chs., then northerly.

80.20

Point for the cor. of secs. 6 and 7, at proportionate distance. Fragments of the old pine post were found lying loose on the ground at this point. However, no evidence remains of the original position of this post.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 26 ins. in the ground, with a juniper post, 8 ft. long, set alongside, with brass cap mkd.

T 9 N

R 60 E R 61 E

S 6

S 7

1953

Dig a trench, 5 ft. diam., and raise a mound of earth, 3 ft. diam., around corner.

Land, nearly level.

Soil, sandy clay.

No timber; undergrowth, sagebrush.

N. $0^{\circ} 03'$ W., along W. bdy. of sec. 6.

Over nearly level land.

40.10

Point for the $\frac{1}{4}$ sec. cor. of sec. 6, at proportionate distance. The remains of the original wooden post was found lying loose on the ground, but no evidence remains of the original location of this post.

Set an iron post, 30 ins. long, 2 ins. diam., 26 ins. in the ground, with brass cap mkd.

 $\frac{1}{4}$ S 6

1953

Dig a trench, 5 ft. diam., and raise a mound of stone, 3 ft. diam., around corner.

From this corner, Gubler windmill bears N. $77^{\circ} 51'$ W.

47.20

Rut road, bears E. and W.