

Dependent Resurvey, Third Standard Parallel North, through R. 61 E.

Chains	Dig a circular trench, 4 ft. diam., 1 ft. deep, and raise a flat mound of earth around the iron post. 39.95 Wash, 10 lks. wide, 1 ft. deep, drains S. for 1 chain, then turns to S. 15° W.; asc. 75 ft. over SE. slope. 45.75 Spur, slopes S. 10° W.; desc. 75 ft. over SW. slope. 53.30 Wash, 10 lks. wide, 1 ft. deep, drains SW.; thence along a S. slope. 57.00 Spur, slopes S. 10° W.; desc. 385 ft. over NW. slope. 79.56 The standard cor. of Ts. 16 N., Rs. 60 and 61 E., mkd. with an old mound of stone and broken juniper post mkd. with scribed Roman numerals on 2 faces. At the corner point Set an iron post, 30 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd. S C T16N R60E R61E S36 S31 1953 from which A juniper, 4 ins. diam., bears N. 24° E., 90 lks. dist., mkd. SC BT. No other bearing tree available. Bury the old marked post alongside, and raise a flat mound of stone, 4 ft. diam., around the iron post. Geographic position of the corner is latitude 39° 12' 09" N., and longitude 115° 09' 30" W. Land, rolling to broken. Soil, sandy and gravelly to rocky. Timber, juniper and pinon; undergrowth, sagebrush, black brush and rabbit brush.
	Dependent Resurvey, W. Bdy. of T. 15 N., R. 62 E., with addition of Survey Corners for E. Bdy. of T. 15 N., R. 61 E.
	Partial Reestablishment of the Survey Executed by E. B. Monroe, Deputy Surveyor, in 1873. Note: Although originally surveyed as a common boundary, due to excessive discrepancies in the original measurements, the corners as originally established will not serve as corners for T. 15 N., R. 61 E. Therefore, the new monuments established at all recovered or proportionate corner positions are marked for sections of T. 15 N., R. 62 E. only. Survey monuments for corners of T. 15 N., R. 61 E. only are established along this line at intervals of 40 and 80 chains of northing, counting from the SE. corner of the township.