

Independent Resurvey, South Boundary, T. 18 N., R. 60 E.

Chains

Set an iron post, 3 ft. long, 2 ins. diam., 27 ins. in the ground, with broken glass deposited at the base, with brass cap mkd.

T18N R60E
S32|S33
 T17N R60E
 S 5
 1945

No suitable accessory.

Land, nearly level.

Soil, sandy clay loam.

Timber, none; undergrowth, sagebrush, shadscale and greasewood.

West, along the S. bdy. of sec. 32.

Over nearly level land, through dense undergrowth.

40.00

Point for the S. $\frac{1}{4}$ sec. cor. of sec. 32.

Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground with broken glass deposited at the base, with brass cap mkd.

$\frac{1}{4}$ S 32

 1945

No suitable accessory.

80.00

Point for the cor. of secs. 31 and 32.

Set an iron post, 3 ft. long, 2 ins. diam., 27 ins. in the ground with broken glass deposited at the base, with brass cap mkd.

T18N R60E
S31|S32
 T17N R60E
 S 6
 1945

Elevation, top of iron post, determined by U.S.G.S., 6368 ft.

No suitable accessory.

Land, nearly level.

Soil, sandy clay loam.

Timber, none; undergrowth, sagebrush, greasewood, and shadscale.

West, along the S. bdy. of sec. 31.

Over nearly level land, through dense undergrowth.

40.00

Point for the S. $\frac{1}{4}$ sec. cor. of sec. 31.

Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground with broken glass deposited at the base, with brass cap mkd.

$\frac{1}{4}$ S 31

 1945

No suitable accessory.