Survey of the Subdivision, T. 20 N., R. 60 E.

Chains	
86.94	Intersect the Fourth Standard Parallel North. Point for the closing cor. of secs. 1 and 2. Set an iron post, 30 ins. long, 2½ ins. diam., 10 ins. in the ground to solid rock, and in a mound of stone, with brass cap mkd. T21N R60E S35 S 2 | S 1 T20N R60E C C 1958 Deposit broken glass at base of iron post. From point of intersection the standard ¼ sec. cor. of sec. 35, T. 21 N., R. 60 E., bears S. 89° 59' W., 11.84 chs. dist. previously described. Land, rolling hills. Soil, gravelly clay loam. Timber, juniper. Undergrowth, sagebrush, bitter brush, weeds and grass.
	At midpoint on the N. bdy. of sec. 1, point for the ¼ sec. cor. Set an iron post, 30 ins. long, 2½ ins. diam., 20 ins. in the ground, and in a collar of stone, with brass cap mkd. ¼ S 1 T20N R60E 1958 Deposit broken glass at base of iron post. From this point the standard cor. of secs. 35 and 36, T. 21 N., R. 60 E., bears S. 89° 59' W., 11.88 chs. dist., previously described.
	From the cor. of secs. 2, 3, 34 and 35 on the S. bdy. of the township, mkd. by an iron post, 2½ ins. diam., conforming to the record of the independent resurvey of the N. bdy. of T. 19 N., R. 60 E., concurrently resurveyed under this same group. N. 0° 01' W., bet. secs. 34 and 35. Over rolling land, through scattered timber and scant undergrowth.
0.90	Shallow wash, drains NE.
25.90	Wash, 25 lks. wide, 3 ft. deep, drains N. 30° W.
40.00	Point for the ¼ sec. cor. of secs. 34 and 35. Set an iron post, 30 ins. long, 2½ ins. diam., 6 ins. in the ground to solid rock, and in a mound of stone, with brass cap mkd. T20N R60E ¼ S34 | S35 1958 Deposit broken glass at base of iron post.
53.05	Wash, 30 lks. wide, 4 ft. deep, drains NE.