

## Survey of the Subdivision, T. 20 N., R. 60 E.

Chains

- 65.70 Shallow draw, drains S.; asc. along rolling SE. slope.  
 74.30 Low spur, projects S.; desc. along rolling SW. slope.  
 80.20 The cor. of secs. 5, 6, 7 and 8.

Land, rolling hills.  
 Soil, gravelly to rocky clay loam.  
 Timber, juniper and pinon.  
 Undergrowth, sagebrush, bitter brush, weeds and grass.

West, bet. secs. 6 and 7.

Over mountainous land, through scattered timber and scant undergrowth;  
 desc. along rolling SW. slope.

- 12.70 Draw, drains SW.; asc. over rolling E. slope.  
 20.00 Spur, projects S.; desc. along NW. slope.  
 28.90 Draw, drains SW.; asc. over E. slope.  
 40.00 Point for the  $\frac{1}{4}$  sec. cor. of secs. 6 and 7.

Set an iron post, 30 ins. long,  $2\frac{1}{2}$  ins. diam., 8 ins. in the ground  
 to solid rock, and in a mound of stone, with brass cap mkd.

T20N R60E

$\frac{1}{4}$   $\frac{S\ 6}{S\ 7}$   
 1958

Deposit broken glass at base of iron post.

- 43.80 Spur, projects SW.; desc. along W. slope.  
 53.70 Draw, drains S.; asc. over E. slope.  
 60.30 Spur, projects W.; desc. over W. slope.  
 65.50 Intersect the E. bdy. of sec. 12, T. 20 N., R. 59 E.

Point for the closing cor. of secs. 6 and 7.

Set an iron post, 30 ins. long,  $2\frac{1}{2}$  ins. diam., 20 ins. in the ground,  
 and in a collar of stone, with brass cap mkd.

T20N  
 R59E R60E  
 S12  $\frac{S\ 6}{S\ 7}$  CC  
 1958

Deposit broken glass at base of iron post.

from which

A pinon, 6 ins. diam., bears N.  $65^{\circ} 08' E.$ , 57 lks. dist.,  
 mkd. T20N R60E S6 CC BT.

From point of intersection the cor. of secs. 1 and 12, T. 20 N., R.  
 59 E., bears N.  $0^{\circ} 19' E.$ , 10.83 chs. dist., previously described.

Land, rolling mountains.  
 Soil, rocky clay loam.  
 Timber, juniper and pinon.  
 Undergrowth, sagebrush, bitter brush, weeds and grass.