

## Dependent Resurvey of the Fourth Standard Parallel North in R. 61 E.

Chains

S C  
T21N R61E  
 $\frac{1}{4}$  S34  
1958

Deposit broken glass at base of iron post.

80.65 The official standard cor. of secs. 33 and 34, mkd. by a decayed juniper post, 2 ins. diam., 2½ ft. long, and having dim scribe marks on two adjacent faces, lying on an old mound of earth.

At the cor. point

Set an iron post, 30 ins. long, 2½ ins. diam., 25 ins. in the ground, with brass cap mkd.

S C  
T21N R61E  
S33|S34  
1958

Deposit broken glass at base of iron post, and set original stake alongside.

Land, level desert.

Soil, deep, heavy clay.

Timber, none; undergrowth, sagebrush, shadscale, greasewood, weeds and grass.

N. 89° 18' W., along the S. bdy. of sec. 33.

Over level land, through medium dense undergrowth.

40.195 Point for the standard  $\frac{1}{4}$  sec. cor. of sec. 33, at proportionate dist.; there is no remaining evidence of the original cor.

Set an iron post, 30 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.

S C  
T21N R61E  
 $\frac{1}{4}$  S33  
1958

Deposit broken glass at base of iron post.

80.39 The official standard cor. of secs. 32 and 33, mkd. by a decayed juniper stake, 2x2x24 ins., lying on an old mound of earth, and having faint scribe marks on two adjacent faces.

At the cor. point

Set an iron post, 30 ins. long, 2½ ins. diam., 26 ins. in the ground, with brass cap mkd.

S C  
T21N R61E  
S32|S33  
1958

Deposit broken glass at base of iron post, and set original stake alongside.