

DEPENDENT RESURVEY OF SUBDIVISION OF T. 20 N., R. 19 E.

Chains	
3.70	Dim road, bears N.20°E. and S.30°W.
17.50	Ravine, drains N.30°E.
35.70	Main channel of large draw, drains N.60°E.
40.13	Intersect the original $\frac{1}{4}$ sec. cor., which is a basalt stone, 4x6x13 ins., mkd. $\frac{1}{4}$ on W. face, firmly set in a small mound of stones. At point for cor., Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, with the original corner stone deposited at the base, for $\frac{1}{4}$ sec. cor., with brass cap mkd. $\frac{1}{4}$ S 5 S 4 1941 raise a mound of stone, 3 ft. base, 1 $\frac{1}{2}$ ft. high, W. of cor. Thence N. 0°11' W., bet. secs. 4 and 5, (north half mile.) 30.80 Wide shallow dry wash, drains NE. 39.24 Intersect the Fourth Std. Parallel North at the reestablished closing cor. of secs. 4 and 5; which is an iron post, 3 ins. diam., set, mkd. and witnessed as described in the field notes of the resurvey of the S. bdy. of T. 21 N., R. 19 E., executed under this group. The std. cor. of secs. 32 and 33 bears S. 89°56' W., 8.93 chs. dist. The std. $\frac{1}{4}$ sec. cor. of sec. 32 bears N. 89°56' E., 31.30 chs. dist. Land, rolling. Soil, shallow coarse gravelly to rocky clay loam, 2nd and 3rd rate. Undergrowth, sagebrush, buck brush. Grazing, fair to poor.
	From the cor. of secs. 28, 29, 32 and 33, S. 88°30' W., bet. secs. 29 and 32, Along rocky S. slope. .80 Head of draw, drains S.60°E.; asc. 160 ft. over broken E. slope through very dense undergrowth. 12.00 Spur ridge, bears N. and S.; desc. 170 ft. over W. slope. 28.30 Draw, drains S.20°W. 33.00 Narrow low gravelly spur, slopes S. 8 chs. to end. 35.90 Ravine, drains S.10°E.; asc. 60 ft. over broken E. slope. 38.91 Proportionate distance; no trace was found of the original corner. Set an iron post, 3 ft. long, 1 in. diam., 24 ins. in the ground, and in a large circular mound of stones, 5 ft. diam., for $\frac{1}{4}$ sec. cor., with brass cap mkd.